No.LS20200079

MONUMENT RECORD


STATE OF INDIANA ~ COUNTY OF MONROE

his monument is not a PLSS of a PLSS			Tie Drawing	eodetic Control	Survey.)
Monument recovered in good condition. Best access is from Arlington Road (aka S.R. 4	16)				
7/24/2018, Cassidy Raley, Fbk. 52, pg. 22	,				
1	1	T 1			i i
		р		Pwr.Pole #40	├
		punoq	28.1	e -	1 1
		S.R.37 North	22.4	Line Marker	
		Siz	97 94.8	_/	
	Overpa			T-Post	A
		T	S.R.46		/
	punoq	-34			4
					N
	S.R.37 South				N.T.S.
			** \$54		s Disk omer = o
				at C	orner – •

I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Indiana Registered Land Surveyor No. LS20200079

COMPLETED BY St. U Fanders



ImageSource: 2014 Monroe County Pictometry

